


- DE** Montageanleitung
FR Instructions de montage
EN assembly instructions
IT Istruzioni per Installazione
ES Instrucciones de montaje
NL Handleiding
DK Monteringsvejledning
PT Manual de Instalação
PL Instrukcja montażu
CS Montážní návod
SK Montážny návod
ZH 组装说明
RU Инструкция по монтажу
HU Szerelési útmutató
FI Asennusohje
SV Monteringsanvisning
LT Montavimo instrukcijos
HR Uputstva za instalaciju
TR Montaj kılavuzu
RO Instrucțiuni de montare
EL Οδηγία συναρμολόγησης
SL Navodila za montažo
ET Paigaldusjuhend
LV Montāžas instrukcija
SR Uputstvo za montažu
NO Montasjeveiledning
BG Инструкция за употреба
SQ Udhëzime rreth montimit
AR تعليمات التجميع




Croma 100 1jet
28580000




Croma 100 Vario
28535000



Croma 100 Multi
28536XXX



Croma 100 1jet
28580000



Croma 100 Vario
28535000

Croma 100 Multi
28536XXX




P max.
0,6 MPa
6 bar

0,1 - 0,4 MPa
1 - 4 bar




T max.
60 °C


40 - 50 °C




Croma 100 1jet 28580000



Croma 100 Vario 28535000




97708000



Croma 100 Multi 28536XXX






Croma 100 Vario

28535000







Croma 100 Multi

28536XXX



	P-IX	DVGW	SVGW	ACS	WRAS	NF	KIWA
28580000	P-IX 7512/IS	CM0350	X	X	X	X	X
28535000	P-IX 18335/ID		X	X	X	X	X
28536XXX	P-IX 18336/ID		X	X	X	X	X





hansgrohe

Hansgrohe · Austraße 5 · 9 · D-77761 Schiltach
 Telefon +49 (0) 78 36/51-1282 · Telefax +49 (0) 7836/511440
 E-Mail: info@hansgrohe.com · Internet: www.hansgrohe.com

3/2016
 9.04.213.06